



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

MARY ANN WRIGHT
Acting Division Director

Supervisor ARH

Inspection Report
Minerals Regulatory Program
Report Date: April 20, 2005

Mine Name: South Hansen Quarry

Operator or Permittee Name:

Geneva Rock Products

Permittee Mailing Address:

15547 South 300 West

Draper, Utah

Inspector(s):

Daron Haddock, Brice Tripp, Doug Jensen

Other Participants:

Carl Clyde, Tony Christofferson

Permit Status: Proposed

Current Acreages:

Total Permitted (Bonded): Under Review

Total Disturbed: Under Review

Permit number: M/035/026

Inspection Date: April 19, 2005

Weather: Partly cloudy, windy, cool

Inspection Start Time: 9:00 AM

Inspection End Time: 12:05 PM

Site location/Area Inspected (i.e. Pit #):

Quarry

Surface Ownership: Fee

Mineral Ownership: Fee

Mineral Mined: Sand, Gravel, Rock
Outcrop

Type of Mine: Quarry

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: April 19, 2005; Report Date: April 20, 2005

Page 2 of 3

M/035/026

Purpose of Inspection:

This visit was made prior to permitting to delineate areas that would fall under the Division's permitting process. Also to review possible areas that would be considered secondary processing; therefore, not included under our permit.

Inspection Summary:

We met with Mr. Clyde and Mr. Christofferson at the South Hansen quarry office where we were shown a 2000 aerial of the site, on which property lines had been placed. Areas were pointed out that were not a part of Geneva's holdings and areas that they believed were exempt from the permitting process.

While some areas were obviously secondary and would be exempt from the permitting process, the separation of the areas through which materials transition from primary to secondary processing was discussed. The delineation of these areas will be much more difficult.

It was suggested that Geneva outline each type of area on a more recent aerial photo. Once this is completed, the Division would make another site visit to refine their effort. When this is completed, an acreage figure can be arrived at for the calculation of the interim bond that was required by the Division during our April 6, 2005 meeting with Geneva. This interim bond will be held until Geneva has completed the permitting process for the site. At the time Geneva has an approved plan, a bond will be calculated for reclamation activities outlined in that plan.

Because of the extent of Geneva's property holdings in the area, future mining plans for the site were discussed. It was stressed that a mine plan for a minimum of five to ten years would be necessary for the initial permit application.

After the discussion, a tour was made of the site. We were shown each of the types of processing areas and the reason why Geneva believed some were not subject to regulation.

We toured from the south to the north end of the quarry, viewing the different operations and working faces. While some of the material in the highwall was obviously sand and gravel, this material was underlain by quartzite material, which is the bedrock portion of the quarry.

We also toured the cut area located on the upper eastern edge of the quarry. All of the material being removed in this area has been identified as quartzite.

As we left the site, we reminded Geneva that they needed to give a written communication to the Division outlining their plans regarding the permitting of the site. During our April 6, 2005 meeting, Geneva stated that they would notify the Division as to their plans pertaining to the permitting of the site.

Inspection Date: April 19, 2005; Report Date: April 20, 2005
Page 3 of 3
M/035/026

1. Permits, Revisions, Transfer, Bonds ---Because of the recent identification of bedrock material in the working faces at the site, Geneva has been notified that it is required this site apply for a mining permit through the Division.
15. Facilities ---There are secondary process areas within the permit area that will need to be identified and eliminated from the permitting process.


Directions to the site:

The site is located at the Point of the Mountain; access is made by taking the Bluffdale exit and turning south on the frontage road.

GPS data:

None gathered on this visit.

Inspector's Signature



Date: April 20, 2005

DJ:jb

Cc: Carl Clyde, Geneva Rock

Tony Christofferson, Geneva Rock

O:\M035-SaltLake\M0350026-GenevaRock\inspections\04192005ins.doc